


MONUMENT RECORD

STATE OF INDIANA ~ COUNTY OF MONROE

Section 1,2,11&12 , Township 9 North , Range 2 West ,

Monument Description & Remarks: Brass plug in \mathcal{C} / \mathcal{C} Union Valley Road and McNeely Street, 0.25' below ground.



COMPLETED BY Stu U. Taylor

I, Ben E. Bledsoe, Registered Land Surveyor, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 27th day of December, 2004 A.D.

Ben E. Bledsoe

Indiana Registered Land Surveyor No. S0559



MONUMENT RECORD

STATE OF INDIANA - COUNTY OF MONROE

SECTION 1,2,11,12, TOWNSHIP 9 NORTH, RANGE 2 WEST

MONUMENT DESCRIPTION & REMARKS

SET BRASS PLATE & ROD IN THE CENTERLINE OF UNION VALLEY ROAD &
MCNEELY STREET, PLATE IS RECESSED INTO THE ASPHALT.

RECOVERY TIE DRAWING

P.K. NAIL ON EAST
SIDE OF 9" P. POLE
NO. 164-952


P.K. NAIL ON
SOUTH SIDE OF
9" P. POLE
NO. 160-329

MCNEELY ST.

UNION VALLEY Rd.

SET MONUMENT

P.K. NAIL ON WEST SIDE
OF 9" P. POLE NO. 160-328



(•) AT CORNER



NOT TO SCALE

STATE OF INDIANA

COUNTY OF MONROE

I, EDMUND O. FARKAS HEREBY CERTIFY THAT THIS
DOCUMENT WAS PREPARED UNDER MY DIRECTION IN ACCORDANCE
WITH THE PROVISIONS OF SECTION 17-3-64-4 - 17-3-64-8 OF
THE INDIANA CODE, BEING ACTS OF 1965, CHAPTER 319; AND
THE ABOVE DATA IS GIVEN UNDER MY HAND AND SEAL
THIS 17 TH DAY OF SEPTEMBER, 1984 A.D.

SPACE
RESERVED
FOR
RECORDING
OFFICER.

INDIANA REGISTERED LAND SURVEYOR NO. _____

OR _____

UNITED STATES GOVERNMENT AGENCY

TITLE _____

TOWNSHIP:
RICHLAND

CORNER I.D.

CORNER I. D.


U-5

MONUMENT RECORD

SECTION 1,2,11,12

TOWNSHIP 9 NORTH

RANGE 2 WEST



RICHLAND TWP.